



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #12893584 - 2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor



Item Details:

- Features: 62 in High Rise Sleeper Cab, Bunk Beds, Paccar MX-13 6 Cylinder 12.9 L Diesel 510 hp Engine, 2022 US EPA Label, 6581 Engine hrs, Air Conditioner, Cruise Control, Power Windows, Engine Brake, Automated Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
- Meter Reading: 304,866 Miles
- Serial # : 1XKYDP9X3PJ2XXXXX
- Inspection Completed: 1/22/25

Shipping Details:

- Location Indiana (Indianapolis area)
- Loading Dock Available: No
- Pickup Hours: 08:00 - 16:00
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★★☆	Performs within the tolerances expected for age and type of item
★★★☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Cab


Item	Assessment	Photo
Cab #1		
Cab #1		
Cab #2		
Cab #3		
Cab #4		

Cab #5		
Cab #6		

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		 A black semi-truck is shown from a left front corner perspective. The truck is parked on a gravel lot under a clear blue sky. The front grille and headlight are visible. An "IRON PLANET" watermark is in the bottom right corner.
Picture, Left Rear Corner		 A black semi-truck is shown from a left rear corner perspective. The truck is parked on a gravel lot. The rear of the cab and the rear wheels are visible. An "IRON PLANET" watermark is in the bottom right corner.
Picture, Right Rear Corner		 A black semi-truck is shown from a right rear corner perspective. The truck is parked on a gravel lot. The rear of the cab and the rear wheels are visible. An "IRON PLANET" watermark is in the bottom right corner.
Picture, Right Front Corner		 A black semi-truck is shown from a right front corner perspective. The truck is parked on a gravel lot. The front grille and headlight are visible. An "IRON PLANET" watermark is in the bottom right corner.
Second Serial Number/VIN Photo		 A close-up photo of the second serial number/VIN. The metal plate is visible, showing the number "U800738". An "IRON PLANET" watermark is in the bottom right corner.
Hour Meter / Odometer	304866 mi	 A photo of the hour meter and odometer. The odometer shows "304,866.7 MI". The hour meter shows "0". A label with "IronPlanet.com" and "U800738" is visible. An "IRON PLANET" watermark is in the bottom right corner.

Motor Vehicle Safety Standards Label	Yes	
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders	Missing components	
Hand Rails		
Glass		
Exterior Lights	Operational	

General Appearance #1		
General Appearance #2		
General Appearance #3		
General Appearance #4		

Brakes / Tires

11/32"
Aluminum

Drum

Drum

14/32"
Aluminum

9/32"
Aluminum

11/32"
Aluminum

Drum

Drum

2/32"
Aluminum

9/32"
Aluminum

10/32"
Aluminum

8/32"
Aluminum

Drum

Drum

0/32"
Aluminum

9/32"
Aluminum

Engine

Item	Assessment	Photo
Emissions Information	2022 US EPA Label	
Emission Label		
A/C Compressor	Operational	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Air Compressor	Operational	
Fuel System	Operational	
Exhaust System		
Diesel Particulate Filter		

Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Engine #1



Cab

Item	Assessment	Photo
Engine Hours	6581 Engine hrs	
Mirrors		
Window Controls	★★★★☆ Both Power	
Seats/armrests	Both seats will not respond to air ride controls	
Seat Belts	Operational	
Steering Control	★★★★☆	
Horn	Air and electric horns are operational	
Oil Pressure	31 PSI	
Warning Lights	Operational	

Gauges	Operational	
Gear Selector	★★★★☆	
Brake Control	Operational	
Engine Brake	Not operationally checked	
ECM Miles	305571 ECM mi	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Underbody

Item	Assessment	Photo
Steering Components	★★★★☆	
Steer Axle	★★★★☆	
Transmission	★★★★☆	
Frame Condition	★★★★☆	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Limited Function Check	The drivetrain was operational without a load.	

Cab Suspension Air Bags	★ ★ ★ ☆	
Suspension Springs/Hangers	★ ★ ★ ☆	
Suspension Bushings	★ ★ ★ ☆	
Suspension Air Bags	★ ★ ★ ☆	
Left Steer Tire		
Left Front Drive Tires		
Left Rear Drive Tires		

Right Rear Drive Tires		
Right Front Drive Tires		
Right Steer Tire		
Wheel Condition	★★★★☆	
Wheel Studs	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational. The park brake is operational.	

Specialty

Item	Assessment	Photo
Fifth Wheel		

Oil Sample Analysis (engine)

Item	Assessment	
date of analysis	Jan 30, 2025	
Silicon	11.31 PPM	
Tin	0 PPM	
Silver	0 PPM	
Aluminum	3.33 PPM	
Chromium	0.54 PPM	
Lead	0 PPM	
Copper	1.31 PPM	
Nickel	0.22 PPM	
Iron	25.2 PPM	
Glycol	NEG	
Water	NEG	
Fuel	<5%	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved